

TO: PURCHASERS OF FANLIGHT, INC. MERCURY VAPOR LAMPS AND METAL HALIDE LAMPS

RE: NOTIFICATION OF PRODUCT DEFECT (per 21 C.F.R. § 1003.21)

You are receiving this notification because our records show that you purchased from Fanlight, Inc. a PLUSRITE brand mercury vapor lamp or metal halide lamp after we first began commercial distribution of the products in the U.S. in March 2003.

1. Products Affected.

All models of the following products are affected by this notice:

PLUSRITE POWERSTRIKE METAL HALIDE LAMP
PLUSRITE LOW WATT METAL HALIDE LAMP
PLUSRITE UNIVERSAL METAL HALIDE LAMP
PLUSRITE PROTECTED METAL HALIDE LAMP
PLUSRITE MERCURY VAPOR LAMP

2. Nature of Product Defect.

Please be advised that these products are defective for failure to comply with the Food and Drug Administration's (FDA's) regulations governing these products. 21 C.F.R. § 1040.30. The Company is taking steps to bring all such products into compliance with these regulations.

3. Potential Health Hazards.

The lack of required markings and warnings on these lamps may contribute to, or exacerbate, injuries that may be sustained from breakage of the outer bulb and resulting exposure of persons to shortwave ultraviolet radiation. The injuries from such exposure can include eye and skin injuries.

4. Disposition of Affected Lamps and Offer for Free Replacement.

Fanlight will, without charge, remedy the defect or bring the product into compliance with each applicable Federal standard in accordance with the following replacement plan, described below. As a part of this offer for a free replacement lamp, you are requested to **return the lamp(s) currently in your possession to Fanlight.**

